

Office Ph #
316-841-5395

Carr's HVAC
Service Price Book

3815 W. Douglas
Wichita KS 67213

NUMBER	REPAIR DESCRIPTION	Base PRIMARY	Base ADDL. REPAIR	AFTER HOURS PRIMARY	AFTER HOURS ADDL.	HDWE
DUCTWORK						
GEN103005	REPAIR PLENUM/TRUNK DUCT CONN	\$95	\$76	\$138	\$110	\$10
GEN103010	REPAIR METAL BRANCH DUCT CONN	\$107	\$85	\$150	\$120	\$21
GEN103015	REPAIR FLEX BRANCH DUCT CONN	\$91	\$73	\$133	\$107	\$4
GEN103020	REPAIR HOLE IN DUCTBOARD	\$99	\$80	\$143	\$114	\$14
GEN152706	AIR BALANCE (NO DIAGNOSTIC CHARGE)	\$172	\$138	\$259	\$206	\$0
GEN152707	ADDITIONAL SYSTEM AIR BALANCE	\$87	\$69	\$129	\$103	\$0
GEN103027	INSTALL METAL ACCESS PANEL	\$105	\$84	\$147	\$118	\$18
GEN103025	INSTALL ROUND DAMPER THRU 12"	\$109	\$87	\$151	\$121	\$23
GEN103026	INSTALL RECTANGULAR DAMPER	\$176	\$142	\$241	\$193	\$47
GEN4E30	1ST ROUND PIPE EL 4-6"	\$70	\$56	\$92	\$73	\$28
GEN4E30	EACH ADDITIONAL EL 4-6"	\$28	\$22	\$34	\$28	\$14
GEN4E30	1ST ROUND PIPE EL 7-9"	\$74	\$61	\$96	\$77	\$32
GEN4E30	EACH ADDITIONAL EL 7-9"	\$32	\$26	\$39	\$32	\$18
GEN4X2P30	ROUND PIPE 4-6" (1ST FT.)	\$66	\$52	\$87	\$70	\$23
GEN4X2P30	EACH ADDITIONAL FOOT 4-6"	\$23	\$18	\$30	\$23	\$10
GEN7X2P30	ROUND PIPE 7-9" (1ST FT.)	\$70	\$56	\$92	\$73	\$28
GEN7X2P30	EACH ADDITIONAL FOOT 7-9"	\$28	\$22	\$34	\$28	\$14
GENFLEX	REPLACE FLEX DUCT 6-14" (1ST FT.)	\$70	\$56	\$92	\$73	\$28
GENFLEX69	EACH ADDITIONAL FOOT 6-9"	\$19	\$15	\$22	\$17	\$14
GENFLEX101	EACH ADDITIONAL FOOT 10-14"	\$30	\$25	\$33	\$26	\$25
GENCAP46	REPLACE 4-6" FLUE CAP	\$142	\$114	\$186	\$149	\$56
GENCAP79	REPLACE 7-9" FLUE CAP	\$180	\$144	\$224	\$179	\$95
GENLINK	FIRE DAMPER FUSE LINK 165 OR 212 DEGREE	\$199	\$160	\$285	\$228	\$28